: DART 5-MAN 3-POINT FWD FACING SHOULDER

User:

Friday, 10/10/2008 1:22:54 PM

Julie Lecocq

Process Sheet

Customer

: CU-DAR001 Dart Helicopters Services

S.O. No. :

Job Number

: 42542

Estimate Number

: 12866

P.O. Number

: 10/10/2008

This Issue

: NC Prsht Rev.

First Issue **Previous Run** : //

: 40132

Type

: SMALL /MED FAB

Drawing Name

HARNESS KIT : D412702043B

Part Number Drawing Number

· IIN D412-702 REV E

: N/A **Project Number** : E **Drawing Revision**

Material

: 14/10/2008 **Due Date**

Qty:

1 Um:

Each

Checked & Approved By

Comment

Written By

: est rev A 07.05.10 new issue EC

est rev C 07.06.20 changed AN44 4A to AN444A EC

Est Rev:D 07-07-06 As per Rev E JLM

Est Rev:E 08-03-31 now at chg003 ECN1150 DD verified by:

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description:

1.0 DC

2.0

3,0

5.0

DOCUMENT CONTROL



JLD 08,10,10

Comment: DOCUMENT CONTROL

Photocopy bluefile & type labels per PPP D412-702-043B CHG003

D412702059

Grommet

Comment: Qty.: 1.0000 Each(s)/Unit Total: **GROMMET KIT**

batch: D412702101B

Harness Assembly

1.0000 Each(s)

Comment: Qty.:

HARNESS ASSEMBLY

1.0000 Each(s)/Unit Total: 1.0000 Each(s)

batch:

D412702103B

Hamess Assembly

Comment: Qty.:

1.0000 Each(s)/Unit

Total:

1.0000 Each(s)

HARNESS ASSEMBLY batch:

D412702105B

Harness Assembly



Comment: Qty.:

1 0000 Each(s)/Unit Total:

1.0000 Each(s)

HARNESS ASSEMBL batch:



_ ~	oopaoo										
W/O:			W	ORK ORDER CHA	ANGES						
DATE	STEP	PROCEDURE CHANGE					Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
						5				1	
				,							
Part No:		PAR #:	Fault Cate	gory:	NCF	NCR: Yes No			DQA: Date:		
Resolution:			Disposition:			QA: N/C Closed: D			Date: _	Date:	
NCR:		V	VORK ORD	ER NON-CONFO	RMANCE	(NCR))				
DATE	STEP	Description of NC		Section B		Verific	ation	Approval	Approval		
DATE	SIEP	Section A	Initial Chief Eng	Action Descript Chief Eng	lion	Sign & Date	Secti	on C	Chief Eng	QC Inspector	
					:						

Friday, 10/10/2008 1:22:54 PM Date: User: Julie Lecocq **Process Sheet** Drawing Name: DART 5-MAN 3-POINT FWD FACING SHOULDER HARNESS Customer: CU-DAR001 Dart Helicopters Services KIT Part Number: D412702043B Job Number: 42542 Job Number: Description: Seq. #: **Machine Or Operation:** 6.0 D412702107B Harness Assembly Somment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) HARNESS ASSEMBLY batch: 7.0 D412702109B Harness Assembly Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Jorgatch HARNESS ASSEMBLY D35421 8.0 2.0000 Each(s)/Unit Total: 2.0000 Each(s) Comment: Qty.: **BRACKET** 32666 batch: D35711 Guide 9.0 Comment: Qty.: 3.0000 Each(s)/Unit Total: 3.0000 Each(s) **GUIDE** 40222 batch: 10.0 D35713 Guide 2.0000 Each(s)/Unit Total: 2.0000 Each(s) Comment: Qty.: **GUIDE** 4653 batch: D3578041 Doubler 11.0 6.0000 Each(s)/Unit Total: 6.0000 Each(s) Comment: Qty.: **DOUBLER** 39376 batch: Bracket D3610041 12.0 Comment: Qty.: 2.0000 Each(s)/Unit Total: 2.0000 Each(s) S 08/16/14 **BRACKET** batch:


W/O:			WO	RK ORDER CHANGE	S			····-	
DATE	STEP	PRO	PROCEDURE CHANGE					Approval Chief Eng / Prod Mgr	Approval QC Inspector
									
	1212								
		PAR #:	Fault Cate	gory:	NCR: Yes No DQA: Date:				
		esolution:	Disposition:				QA: N/C Closed: Date: _		
NCR:			WORK ORDE	ER NON-CONFORMAI	NCE (NC	R)			
D.4.T.F.	0755	Description of NC Section A		ı B	Verific	cation	Approval	Approval QC Inspector	
DATE	STEP		Initial Chief Eng	Action Description Chief Eng	Sign Date	& Sect	Section C		
									<u> </u>
								•	_
*								r t	
			,						
L									

	e Lecocq	. 1.22.07 (19)	Process SI	heet		
Customer:	: CU-DAR001	Dart Helicopters Services	Draw	wing Name: DART 5-MAN 3-P	OINT FWD FACING	SHOULDER HARNESS
	. 40540			KIT		
Job Number:	42542	A 10 110 A 1 A 110 A 10 A 10 A 10 A 10	Pa	ert Number: D412702043B	<u> </u>	
OOD NUITIDEL.						
Seq. #:	Machine Or	Operation:		Description :		
13.0	D36181		CAP			
Comm	•	.0000 Each(s)/Unit Total :	2.0000 Each(s)		1 -	
	CAP batch:	32426				08/6/14 (X)
14.0	AN410A	y -	Bolt			· · · · · · · · · · · · · · · · · · ·
Comm	- ,	.0000 Each(s)/Unit Total :	4.0000 Each(s)			,
	Bolt batch:	107178			S	8/6/14 0
15.0	AN444A		Bolt			
Comm	•	.0000 Each(s)/Unit Total :	2.0000 Each(s)		18	
· .	bolt batch:	164866			187	08/10/14 C
16.0	MS24693S274	\$ 	Screw			
Comm		.0000 Each(s)/Unit Total :	2.0000 Each(s)		1 0	
	Screw batch:	M108560				08/6/M (X)
17.0	MS24694S56	1 	SCREW		/ - 	, –
Comm		.0000 Each(s)/Unit Total:	3.0000 Each(s)		10	
• .	SCREW batch:	M164407			183	08/10/14 (RI
18.0	MS24694S58	8 BJ 1846 (1811) 38 H 1811	Screw			* .
Comm	ent: Qty.: 2.	.0000 Each(s)/Unit Total :	2.0000 Each(s)		10	
	batch:	M104407			43	08/10/14 XI
19.0	MS24694S60		Screw			, —
				·		
Comm	ent: Qty.: 1. Screw	.0000 Each(s)/Unit Total :	1.0000 Each(s)		10	
·	batch:	M104407			130	D8/10/14 RE
Page 2						Form: rprocess
Page 3		-				r omi. ipioossa


W/O:			WO	RK ORDER CHANG	ES	. • .				
DATE	STEP	PROCEDURE CHANGE				Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
		,								
Part No:		PAR #:	Fault Categ	gory:	NCR: Yes	No DQ	A:	Date:		
Resolution		esolution:	Disposition	n:	QA: N/C Closed: Date:					
NCR:			WORK ORDE	R NON-CONFORMA	NCE (NC	R)				
DATE	STEP	Description of NC Section A	Corrective Action Section			Verific	cation	Approval	Approval	
DATE			Initial Chief Eng	Action Description Chief Eng	Sign Date	& Sect	ion C	Chief Eng	QC Inspector	
					į					
	3									
					e i					
	1		1 1		1	ł		1	1	

Date: Friday, 10/10/2008 1:22:54 PM Julie Lecocq User: " **Process Sheet** Drawing Name: DART 5-MAN 3-POINT FWD FACING SHOULDER HARNESS Customer: CU-DAR001 Dart Helicopters Services **KIT** Part Number: D412702043B Job Number: 42542 Job Number: Description: Seq. #: **Machine Or Operation:** Washer 20.0 AN960JD416 6.0000 Each(s) 6.0000 Each(s)/Unit Total: Comment: Qty.: Washer M108827 batch: AN960JD416L 21.0 4.0000 Each(s) Comment: Qty: 4.0000 Each(s)/Unit Total: Washer 4108583 batch: 22.0 MS21042L4 6.0000 Each(s)/Unit Total: 6.0000 Each(s) Comment: Qty.: Nut MICSHY CR321244 Cherry Rivet 23.0 12.0000 Each(s) 12.0000 Each(s)/Unit Total: Comment: Qty.: Cherry Rivet <u>M</u>6929 INSPECT 100% KITS FOR COMPLETENESS 24.0 QC4 Comment: INSPECT 100% KITS FOR COMPLETENESS PACKAGING RESOURCE #1 25.0 **PACKAGING** Identify and pack for shipping as per PPP D412-702-043B CHG003 Location: PPP Rev FINAL INSPECTION/W/O RELEASE QC21 26.0 Comment: FINAL INSPECTION/W/O RELEASE h 800 Job Completion Form: rprocess Page 4

	. oopao								
W/O:			WO	RK ORDER CHANG	ES				
DATE	STEP	PRO	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
		-							
		PAR #:	Fault Categ	ory:	NCR: Yes	No DQ	lo DQA: Date		
		esolution:	Disposition	:	QA: N/C Closed:			Date: _	
NCR:			WORK ORDE	R NON-CONFORMA	NCE (NCR)			
		Description of NC	Corrective Action Se		on B	Verific	cation	Approval	Approval
DATE	STEP Description of NC Section A		Initial Chief Eng	Action Description Chief Eng			Section C Chief Eng	QC Inspector	
				•		ļ			
									i.
								i	
	,	:							
		,							



DETAIL 'K' D412-702-101A/-103A/-105A/-107A/-109A/-115A/-117A AND D412-702-101B/-103B/-105B/-107B/-109B/-115B/-117B HARNESS ASSEMBLIES (BELTS, K6.2 CLIP AND D3569-1/-2/-3 DECAL NOT SHOWN)



DETAIL 'L' D412-702-111A/-111B/-113A/-113B HARNESS ASSEMBLIES (BELTS AND D3569-1/-2/-3 DECALS NOT SHOWN)

SHOP COPY RETURN TO **ENGINEERING** UNCONTROLLED COPY SUBJECT TO AMENDMENT WITHOUT NOTICE WARRENDER

• COPYRIGHT © 2004 BY DART AEROSPACE LTD. •
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

25-00-00